

0031

7050



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

gch BR7

INSPECTION REPORT

INSPECTION DATE & TIME: 12/20/90, 1:30 - 3:30pm

Permittee and/or Operators Name: Genwal Coal Company (801) 687-9813

Business Address: P.O. Box 1201, Huntington, UT 84528

Mine Name: Crandall Canyon Mine Permit Number: ACT/015/032

Type of Mining Activity: Underground ☒ Surface ☐ Other ☐

County: Emery

Company Official (s): Allen Childs, Jay Marshall, Randal Ralphs, Lannie Burnside

State Official(s): Priscilla Burton, Steve Demzak

Partial: ☒ Complete: ☐ Date of Last Inspection: 11/20/90

Weather Conditions: Clear and freezing temperatures

Acreage: Permitted 532.36 Disturbed 5.55 Regraded 0.5 Seeded 0.5 Bonded 9.7

Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---------------------------------------------------------------------|-----|-----|-----|----------|
| 1. PERMITS | (X) | () | () | (X) |
| 2. SIGNS AND MARKERS | (X) | () | () | () |
| 3. TOPSOIL | () | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | (X) | () | () | () |
| b. DIVERSIONS | (x) | () | () | () |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | (X) | () | () | () |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | () | () | () | () |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | (X) | () | () | (X) |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | () | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | () | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | () | () | () | () |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | (X) | () | () | (X) |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | (X) | () | () | (x) |

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032 Genwal Coal Co.
12/20/90

DATE OF INSPECTION:

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The Legal description of the Lease areas SL-062648 and U-54762 came under review at the request of Genwal Coal Co. The legal descriptions in the BLM Lease agreement, the BLM "Status & Encumbrance Map," letters of correspondence and Plate 2.1 of the MRP are currently being reviewed and checked against the information contained at the Emery Co. courthouse and the BLM office in Salt Lake City.

6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL

The Operator's intention to construct a more effecient crusher/conveyor belt along the Forest Service road will eliminate any temporary storage capacity for development waste rock. The use of this area is currently described as temporary development waste rock storage in the MRP and in the NEICO State Lease modification to the MRP. Genwal Coal Co. must develop a new plan for temporary storage of this material in a revised MRP.

17. OTHER TRANSPORTATION FACILITIES

Genwal Coal Co. has applied for an amendment to the MRP to construct a new conveyor belt/crusher system that will allow them to accomodate an increase in production from the new NEICO State Leases ML-21568 and ML-21569.

18. SUPPORT FACILITIES

Construction of the oil storage apron is complete.

Construction of the Shop is underway (located in the same location as the old storage shed and erroneously refered to as a bath house in the last inspection report).

Plans for construction of the conveyor belt/crusher system call for placement of approximately 20' of additional culvert along the Forest Service Road disturbed drainage collection system.

Copies of this report:

Mailed to: Brian Smith - OSM, Jay Marshall - Genwal Coal Co.

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number: Donella Burton, #37
Date: 12.31.90